



SEWING MACHINE TABLE

COMFORT 8

СТОЛ ДЛЯ ШВЕЙНОЙ МАШИНЫ



SYMBOLS



ATTENTION

ВНИМАНИЕ




ASSEMBLY & ADJUSTMENT

СБОРКА РЕГУЛИРОВКА




OPERATION

ЭКСПЛУАТАЦИЯ



INDICATING MARK



ОБОЗНАЧЕНИЕ









EVEN SURFACE

РОВНАЯ ПОВЕРХНОСТЬ

010001	1x	010002	1x	010003	1x	010004	1x
010006	1x	010007	1x	010011	2x	010012	2x
010013	2x	010023	1x	010024	1x	010025	1x
010026	1x	010027	1x	010029	1x	010030	1x
010031	1x	010033	1x				

 020001 2x	 020002 2x	 020003 1x	 020004 1x	 020005 1x
---	---	--	---	---







 020006 1x	 020008 1x	 020009 L300 1x	 020010 L660 1x	 020011 1x	 020012 1x
---	---	--	---	---	---

 2x 020013 CR	 2x 020013 CL
--	--

 2x 020015 DR	 2x 020015 DL
--	--

 020021 4x	2 x 020022 
---	---

 030001 3 * 16 45x	 030002 3,5 * 16 16x	 030003 6,2 * 50 22x	 030004 φ5 * 30 4x	 030005 4,2 * 16 3x	 030006 2,9 * 13 4x
---	---	---	--	--	--

 030008 φ4 2x	 030009 M4 * 20 2x	 030011 φ15 22x	 030012 φ18 10x	 030013 L = 35 10x	 030014 φ15 h12 10x
--	---	--	--	---	--

 030015 φ8 * 30 14x	 030016 φ8 * 30 4x	 030017 φ15 h12 4x	 030022 M 10 4x	 030023 φ 10 4x	 030024 5 * 50 2x
--	---	---	---	--	--

1x  S3	1x  S4
---	---



S 4



010002

010001

3

2 x 030006


1 x



020004


5

6 x 030013



6 x 030015

4



010003

010004

6

6 x 030014



6 x 030012



2 4 x 030011
4 x 030003



010006



1 020001
2 x
2 x 030004




1 020002
2 x
2 x 030004





12 030002
4x 
 020008
1x 



13 020005
1x 
 030001
1x 



9 
2x 020022
4x 
 030001




14 030006
2x 
1x 
 020012

010007

8 020011
1x 
4x 
 030002

7 020003
1x 
3x 
 030005

11 030008 030009
2x 
1x 
 020006

10 020010
1x 020010
22x 
 030001



S3 S4 S5 S12



18 6x 030011
6x 030003

010030

15

030002
4x

2x 020013 CR

010027

16

030003
4x
030011
4x

010024

17

030003
6x
030011
6x

010033

010031

010026

010025

19


4x 030022



4x 030023


4x 020021

15

020013 CL
2x
030002
4x







28

4x 030001


2x 020015 DR

030016 **26**

4x

27

4x 030017





28

2x 020015 DL



4x 030001

25

4x 030015



4



030024

020022

5

